

CLASSIFIED MESSAGE

DATE 0449Z 21 DEC 62

~~TOP SECRET~~

ROUTING

1	2	3
4	5	6

TO : DIRECTOR

FROM [ ]

25X1A ACTION: OPS (1-2-3-4-5)

INFO : S/C (6)

TOR 0456Z 21 DEC 62

~~OPERATIONAL IMMEDIATE~~

OPERATIONAL IMMEDIATE

IN 60054

EDD 90

WER

KB

RLP

RDO

PAG

SAH

25X1A

TO [ ]

INFO

CITE [ ]

25X1A

A. GRC-133

25X1A

B. [ ] 21/0405Z

25X1A

25X1A

C. AT 085 THE [ ] MALFUNCTIONED. UP TO THIS POINT THE

FLIGHT LINE WAS UNDERCAST. DRIVER ATTEMPTED TO RECYCLE [ ]

AND SELECTED ALTERNATE MODES SEVERAL TIMES BUT COULD NOT CORRECT

THE MALFUNCTION. DRIVER ABORTED AND RETURNED TO HOME AT POINT

E50. A.C. GEN FAILED 40 MIN PRIOR TO LANDING. 600 FEET OF FILM

WAS EXPOSED. RECOMMENDATION HERE IS THAT WE PROCESS LOCALLY.

ADVISE ASAP ON YOUR DECISION. IF YOU AGREE, REQUEST YOU INITIATE

ACTION TO CANCEL AIRLIFT.

D. NONE

-END OF MSG-

DOCUMENT NO. \_\_\_\_\_

DO CHANGE IN CLASS. ☐

☐ DECLASSIFIED

CLASS. CHANGE TO: TS (S) C

NEXT REVIEW DATE: \_\_\_\_\_

AUTH: HR 10-2

DATE: 30 Sept 86 REVIEWER [ ]

25X1A

~~TOP SECRET~~

GROUP 1  
Excluded from automatic  
downgrading and  
declassification